



PP-R PIPING SYSTEM

www.rifeng.com



Hot Water Pipe PN 20 / SDR 6

Working Temperature : 3-95 degrees celsius

Working Pressure : PN 20

Standard : ISO 15874 / DIN 8077/78

Physical Feature : Two Red Lines

Cold Water Pipe PN 10 / SDR 11

Working Temperature : 3-60 degrees celsius

Working Pressure : PN 10

Standard : ISO 15874 / DIN 8077/78

Physical Feature : Two Blue Lines

Swallow Tailed Structure



Fittings, Tools, Accessoryies



Insattlation



Step 1:
Cut the pipe vertically and clean the cutting head.



Step 2:
Mark down the length of the hot melting.



Step 3:
Heat up the pipe and fitting at the same time.



Step 4:
Melt the pipe and fitting stably, quickly and directly in a short time.

Contact